



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**16215-37-1774**  
State Number  
**27484**

EQUIPMENT INSPECTED

State Number: <b>27484</b>	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: OTIS	Speed: 100
Landings: 2	Installed: 08/16/2010	Rope Size:
Volts: 208	Complied:	Entrances: 1
OWNER	OCCUPANT	
COX TOYOTA	COX TOYOTA	
DANBROOK ROAD	DANBROOK ROAD	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 08/02/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 37 - Hopper	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	--------------------------	--------------------

1

VIOLATIONS

- 8.6 REMOVE ALL DEBRIS FROM EQUIPMENT ROOM NOT PERTAINING TO ELEVATOR
- 8.6 PUT THE MACHINE ROOM LIGHTS IN WORKING ORDER

Items must be corrected by: 09/01/2016

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: WILLIAM LENNON 336-226-6361

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

COX TOYOTA  
DANBROOK ROAD  
BURLINGTON, NC, 27215