## NCDOL NCDOL

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 16217-48-0134 State Number 17723

10

	]	EQUIPMENT INSPECTED			
State Number: 17723 Capacity: 3000 Landings: 4 Volts: 208 OWNER ISLANDER INN 57 W FIRST ST	Manuf: OTIS Installed: 06/30	Installed: 06/30/1998 Complied: 06/30/1998 OCCUPANT ISLANDER INN 57 W FIRST ST		Floor to Floor: G to 2 Speed: 125 Rope Size: Entrances: 1	
OCEAN ISLE, NC, 28469	IN	OCEAN ISLE, NO	C, 28409 		
Inspection Date 08/04/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	
		VIOLATIONS			
-	signs shall be provided. Damaged or r ter from the pit floor. [2FT OF WATE tor pit.		ZND FLJ		
Items must be corrected by					
Notify the Elevator Bureau in v complainace with current code	writing on Corrected Violations Form s.	when the following corrections	have been made in order to	bring your equipment into	
Violations pointed out to: MGMT.			Inspector		
THIS IS NOT AN INVOICE	To make changes to the invoice material and invoice will be mailed to:		33-0372		