



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
16217-48-1018
State Number
20869

EQUIPMENT INSPECTED

State Number: 20869	Type of Unit: Passenger	Floor to Floor: 1 to 4
Capacity: 2500	Manuf: OTIS	Speed: 100
Landings: 4	Installed: 02/04/2003	Rope Size: 0
Volts: 208	Complied: 02/04/2003	Entrances: 1
OWNER	OCCUPANT	
1769 HORBORAGE CONDO	1769 HORBORAGE CONDO	
1769 HORBORAGE DR.	1769 HORBORAGE DRIVE	
OCEAN ISLE, NC, 28469	OCEAN ISLE, NC, 28469	

INSPECTION INFORMATION

Inspection Date 08/04/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------	---------------------------------	--------------------------	---------------------

10

VIOLATIONS

- 2.7.2.2.1 Provide clear access to the machine room.
- 8.11.2.2.2 Perform the annual no load safety test
- 8.6.4.8.2 Remove all materials from machine room (machinery space) not pertaining to the maintenance or operation of the elevator(s).
- 2.2.2.4 Install the cover on the sump pump.

Items must be corrected by: 10/04/2016

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: UNAVAILABLE

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

1769 HORBORAGE CONDO
1769 HORBORAGE DR.
OCEAN ISLE, NC, 28469