



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
16229-8-0499
State Number
8209

EQUIPMENT INSPECTED

State Number: 8209	Type of Unit: Passenger	Floor to Floor: 1 to 3
Capacity: 2000	Manuf: OTIS	Speed: 100
Landings: 3	Installed: 12/16/1975	Rope Size:
Volts: 208	Complied: 12/09/2002	Entrances: 1
OWNER	OCCUPANT	
ALAMANCE COMMUNITY COLLEGE	ALAMANCE COMMUNITY COLLEGE	
1247 JIMMIE KERR ROAD	1247 JIMMIE-KERR ROAD	
GRAHAM, NC, 27253	GRAHAM, NC, 27253	

INSPECTION INFORMATION

Inspection Date 08/16/2016	Type Inspection Compliance	Certificate Status Prev Issued	Inspector 8 - Burris	County ALAMANCE
-------------------------------	-------------------------------	-----------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.6.4.7	STOP WATER LEAK IN ELEVATOR MACHINE ROOM & REMOVE WATER OFF MACHINE ROOM FLOOR
NCAC	KEEP COPY OF ELEVATOR CERTIFICATE POSTED INSIDE ELEVATOR
8.6.1.4	KEEP MONTHLY UPDATED FIRE SERVICE TEST LOG IN ELEVATOR MACHINE ROOM
2.7.9.2	RESTORE FUNCTION OF ELEVATOR MACHINE ROOM AC UNIT.
8.6.4.10.1	INSTALL MISSING ELEVATOR CAR DOOR RESTRICTOR
8.6.5.5.1	REPLACE JACK SEAL
8.6.4.7	REMOVE HYDRAULIC OIL OFF PIT FLOOR
2.7.3.4.1	MAKE MACHINE ROOM DOOR SELF CLOSE & LOCKING

Items must be corrected by: 10/16/2016

Elevator Name: MAIN BLDG #1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: RONNIE KANUPPS (MAINT)

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ALAMANCE COMMUNITY COLLEGE
1247 JIMMIE KERR ROAD
GRAHAM, NC, 27253