

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number **16231-70-3916** State Number **26637** 

	EQU	IPMENT INSPECTED			
State Number: 26637	Type of Unit: Passe	enger	Floor to Floor: 1 to 3		
Capacity: 2100	Manuf: VERTICAL		Speed: 80		
Landings: 3	Installed: 03/04/200	)9	Rope Size:		
Volts: 208	Complied: 03/04/20	)09	Entrances: 1		
OWNER		OCCUPANT			
ANSON COUNTY GOVERNMENT		ANSON COUNTY ADMIN OFB			
101 S GREENE STREET		101 S GREENE STREET			
WADESBORO, NC, 28170		WADESBORO, NC, 28170			
	INSPE	CTION INFORMATION			
Inspection Date 08/18/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 70 - Darnley	County ANSON	
3.6.1.6.5 Provide a class "ABC" fire e	=				
8.6.4.8.2 Articles or materials not necessary	essary for the maintenance or oper	ration of the elevator shall not be	stored in machine rooms and ma	achinery space	
Items must be corrected by: 10/18/2016		Elevator Name: #1 PASSE	ENGER ELEVATOR		
Notify the Elevator Bureau in writing or complainace with current codes.	n Corrected Violations Form wher	n the following corrections have	been made in order to bring your	r equipment into	
Violations pointed out to: .			Inspector		
	ake changes to the invoice mailing				
THIS IS NOT AN INVOICE An ir	nvoice will be mailed to:	ANSON COUNTY GOVERN 101 S GREENE STREET WADESBORO, NC, 28170	MENT		