

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
www.nclabor.com/elevator.htm  
919-807-2770

Report Number <b>16243-63-3236</b> State Number <b>2153</b>
--

EQUIPMENT INSPECTED

State Number: <b>2153</b>	Type of Unit: Freight	Floor to Floor: 1 to 3
Capacity: 4000	Manuf: MONARCH	Speed: 60
Landings: 3	Installed: 07/22/1953	Rope Size:
Volts: 550	Complied: 07/22/1953	Entrances: 2
OWNER		OCCUPANT
INTERNATIONAL TEXTILE GROUP, INC.		BURLINGTON FINISHING
906 ANTHONY ST		906 ANTHONY ST
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215

INSPECTION INFORMATION

Inspection Date 08/30/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 63 - Yarbrough	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-----------------------------	--------------------

1

VIOLATIONS

8.6.4.7.1 Clean the elevator pit.

Items must be corrected by: 10/30/2016

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Mack Johnson, 336-266-3475

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

INTERNATIONAL TEXTILE GROUP, INC.  
906 ANTHONY ST  
BURLINGTON, NC, 27215