

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 16243-63-4383 State Number 3044

1

]	EQUIPMENT INSPECTED			
State Number: 3044	Type of Unit: Pa	ıssenger	Floor to Floor: 1 to	2	
Capacity: 1000	Manuf: MONARCH		Speed: 75		
Landings: 2	Installed: 08/25/1957		Rope Size:		
Volts: 208	Complied: 08/25	5/1957	Entrances: 1		
OWNER	OCCUPANT				
FIRST CHRISTIAN CHURCH	FIRST CHRISTIAN CHURCH				
PO BOX 1678	415 S CHURCH ST				
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215				
	IN	SPECTION INFORMATION			
Inspection Date	Type Inspection	Certificate Status	Inspector	County	
08/30/2016	Routine	Re-issued	63 - Yarbrough	ALAMANCE	
		VIOLATIONS			
Items must be corrected by: 10)/30/2016				
Notify the Elevator Bureau in writ omplainace with current codes.	ing on Corrected Violations Form	when the following corrections	s have been made in order to brin	ng your equipment into	
Violations pointed out to: Front Office			Inspector		
THIS IS NOT AN	To make changes to the invoice materials. An invoice will be mailed to:		733-0372		