



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**16265-37-2236**  
State Number  
**819**

EQUIPMENT INSPECTED

State Number: <b>819</b>	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 2000	Manuf: MONARCH	Speed: 50
Landings: 2	Installed: 01/21/1947	Rope Size: 1/2
Volts: 220	Complied: 01/21/1947	Entrances: 2
OWNER	OCCUPANT	
THE GLASS ANGEL	THE GLASS ANGEL	
224 EAST FRONT STREET	224 EEAST FRONT ST	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 09/21/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 37 - Hopper	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	--------------------------	--------------------

1

VIOLATIONS

- 8.7 REPLACE THE GOVERNOR ROPE
- 8.6 TAKE STEPS TO ELIMINATE TRIPPING HAZARD AT TOP LANDING
- 8.6 REPLACE THE DAMAGED EQUIPMENT ROOM FLOOR AND ROOF

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: DENNIS LITTELL 336-227-1231

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

THE GLASS ANGEL  
224 EAST FRONT STREET  
BURLINGTON, NC, 27215