N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
16323-48-0372
State Number
H2701

EQUIPMENT INSPECTED

State Number: **H2701**
Capacity: 750
Landings: 2
Volts: 120

Type of Unit: Hand Lift
Manuf: GARAVENTA
Installed: 10/27/2015
Complied: 10/27/2015

Floor to Floor: 1 to 2
Speed: 10
Rope Size:
Entrances: 2

OWNER
BRADFORD PRDUCTS
2101 ENTERPRISE DRIVE
LELAND, NC, 28451

OCCUPANT
BRADFORD PRDUCTS
2101 ENTERPRISE DRIVE
LELAND, NC, 28451

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County
11/18/2016	Routine	Re-issued	48 - Martin	BRUNSWICK

10

VIOLATIONS

Elevator Name: # 1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: MARK MILLER

Inspector _____

THIS IS NOT AN INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:
BRADFORD PRDUCTS
2101 ENTERPRISE DRIVE
LELAND, NC, 28451