



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
16334-37-1044
State Number
8437

EQUIPMENT INSPECTED

State Number: 8437	Type of Unit: Freight	Floor to Floor: 1 to 3
Capacity: 10000	Manuf: SOUTHERN	Speed: 60
Landings: 3	Installed: 07/25/1988	Rope Size:
Volts: 480	Complied: 04/25/1989	Entrances: 1
OWNER	OCCUPANT	
NOVA FLEX HOSE CO	NOVA FLEX HOSE CO	
449 /TROLLINGWOOD ROAD	449 TROLLINGWOOD ROAD	
HAW RIVER, NC, 27258	HAW RIVER, NC, 27258	

INSPECTION INFORMATION

Inspection Date 11/29/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 37 - Hopper	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	--------------------------	--------------------

1

VIOLATIONS

8.11.3.2.1	Perform the annual relief valve test
8.6	REPAIR/ REPLACE THE REAR CAR GATE
8.6	CLEAN AND LUBE ALL WORKING PARTS
8.6	UPDATE THE MAINT RECORDS
8.6	PATCH THE HOISTWAY AS NEEDED

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: KENNETH JONES 336-578-2161

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

NOVA FLEX HOSE CO
449 /TROLLINGWOOD ROAD
HAW RIVER, NC, 27258