



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**16334-37-4194**  
State Number  
**17093**

EQUIPMENT INSPECTED

State Number: <b>17093</b>	Type of Unit: Passenger	Floor to Floor: LL to 3
Capacity: 2500	Manuf: OTIS	Speed: 125
Landings: 4	Installed: 06/23/1997	Rope Size: 3/8
Volts: 480	Complied: 08/04/2003	Entrances: 1
OWNER	OCCUPANT	
BURLINGTON INSURANCE GROUP	BURLINGTON INSURANCE GROUP	
238 INTERNATIONAL	238 INTERNATIONAL	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 11/29/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 37 - Hopper	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	--------------------------	--------------------

1

VIOLATIONS

8.6.4.15	Take steps to place the car emergency light in proper working order. (telephone, ventilation)
8.6.4.7.1	Clean the elevator pit.
2.27.1.1.2	Put the in car emergency telephone in proper working order.
8.6	UPDATE THE MAINT. RECORDS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: JAMES TAYLOR 336-586-2962

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

BURLINGTON INSURANCE GROUP  
238 INTERNATIONAL  
BURLINGTON, NC, 27215