



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
16335-7-387
State Number
H1027

EQUIPMENT INSPECTED

| | | |
|----------------------------|-------------------------|------------------------|
| State Number: H1027 | Type of Unit: Hand Lift | Floor to Floor: 1 to 2 |
| Capacity: 495 | Manuf: GARAVENTA | Speed: 20 |
| Landings: 2 | Installed: 02/01/2000 | Rope Size: 8mm |
| Volts: 220 | Complied: 02/21/2000 | Entrances: 2 |
| OWNER | OCCUPANT | |
| ASHE CO SCHOOLS | ASHE CO MIDDLE SCHOOL | |
| PO BOX 604 | 255 NORTHWEST DR | |
| JEFFERSON, NC, 28640 | WARRENSVILLE, NC, 28693 | |

INSPECTION INFORMATION

| | | | | |
|-------------------------------|----------------------------|---------------------------------|--------------------------|----------------|
| Inspection Date 11/30/2016 | Type Inspection Routine | Certificate Status Re-issued | Inspector 7 - Hoffman | County ASHE |
|-------------------------------|----------------------------|---------------------------------|--------------------------|----------------|

5

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: KENNY RICHARDSON 336-246-7175

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ASHE CO SCHOOLS
PO BOX 604
JEFFERSON, NC, 28640