



INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**16336-48-1681**  
State Number  
**21706**

EQUIPMENT INSPECTED

State Number: <b>21706</b>	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: OTIS	Speed: 125
Landings: 2	Installed: 08/28/2003	Rope Size: 0
Volts: 208	Complied: 08/28/2003	Entrances: 1
OWNER	OCCUPANT	
SOUTHERN SHORE VILLAS HOA	SOUTHERN SHORE VILLAGE	
122 SE 58TH. ST	122 SE 58TH ST	
OAK ISLAND, NC, 28645	OAK ISLAND, NC, 28645	

INSPECTION INFORMATION

Inspection Date 12/01/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------	---------------------------------	--------------------------	---------------------

10

VIOLATIONS

2.27.1.1.2	Put the in car emergency telephone in proper working order.
8.6.4.8.1	Clean the elevator machine room. [2ND. YR.]
2.2.2.4	Install the cover on the sump pump. [2ND. YR.]
2.2.2.4	Put the sump pump in proper working order.
8.6.4.7.4	Remove the water from the pit floor.

Items must be corrected by: 02/01/2017

Elevator Name: # 1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: UNAVAILABLE

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

SOUTHERN SHORE VILLAS HOA  
122 SE 58TH. ST  
OAK ISLAND, NC, 28645