

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 16354-73-4615 State Number 10531

	EC	QUIPMENT INSPECTED			
State Number: 10531 Type of Unit: Passen		nger Floor to Floor: 1 to 3		1 to 3	
Capacity: 4000	Manuf: THYSSEN KRUPP Installed: 08/17/1983		Speed: 100	Speed: 100 Rope Size:	
Landings: 3			Rope Size:		
Volts: 200	Complied: 08/17/1983		Entrances: 1	Entrances: 1	
OWNER	OCCUPANT				
TWIN LAKES CENTER		TWIN LAKES CENTER			
100 WADE COBLE DR		100 WADE COBLE DR			
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215			
	INSI	PECTION INFORMATION			
Inspection Date 12/19/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE	
		VIOLATIONS			
otify the Elevator Bureau in wri	ting on Corrected Violations Form w	hen the following corrections have	e been made in order to br	ing your equipment into	
Violations pointed out to: Maintenance			Inspector		
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	TWIN LAKES CENTER 100 WADE COBLE DR BURLINGTON, NC, 27215			