



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**16355-73-4510**  
State Number  
**14232**

### EQUIPMENT INSPECTED

State Number: <b>14232</b>	Type of Unit: Passenger	Floor to Floor: B to 3
Capacity: 4000	Manuf: THYSSEN KRUPP	Speed: 125
Landings: 4	Installed: 08/22/1991	Rope Size:
Volts: 460	Complied: 08/22/1991	Entrances: 1
OWNER	OCCUPANT	
KOURY PROPERTIES CENTER	KOURY MANANGMENT	
PO BOX 850	3060 S CHURCH ST	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

### INSPECTION INFORMATION

Inspection Date 12/20/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

### VIOLATIONS

5.1.21.1	Put the in car alarm bell in working order.
2.27.3.1	Put the Phase I fire service feature in proper working order.
2.14.7.1.3	Put the in car emergency light in working order.
8.6	Replace missing pick up rollers
8.6	Place in case of fire signs at each landing

Items must be corrected by: 02/20/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Steve

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

KOURY PROPERTIES CENTER  
PO BOX 850  
BURLINGTON, NC, 27215