

THIS IS NOT AN

INVOICE

An invoice will be mailed to:

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 16363-73-4730 State Number 17540

EQUIPMENT INSPECTED				
State Number: 17540	Type of Unit: Passenger		Floor to Floor:	1 to 2
Capacity: 2100	Manuf: THYSSEN KRUPF		Speed: 95	
Landings: 2	Installed: 09/02/1998		Rope Size:	
Volts: 200	Complied: 09/02/1998		Entrances: 1	
OWNER		OCCUPANT		
FIRST PRESBYTERIAN CHURCH		FIRST PRESBYTERIAN CHURCH		
508 W DAVIS ST		508 W DAVIS ST		
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215		
	INSPECTIO	N INFORMATION		
Inspection Date 12/28/2016	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
	VIC	DLATIONS		
8.6 Elevator equipment room8.6 Place in case of fire sign	n not to be used for storage at each landing			
1 1				
8.6 Place in case of fire sign Items must be corrected by: 02.	at each landing	following corrections hav	e been made in order to bri	ng your equipment into

FIRST PRESBYTERIAN CHURCH

508 W DAVIS ST BURLINGTON, NC, 27215