



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
16364-73-4860
State Number
N1.44

EQUIPMENT INSPECTED

State Number: N1.44	Type of Unit: Freight	Floor to Floor: to
Capacity: 1200	Manuf: MOFFAT	Speed: 75
Landings: 3	Installed: 04/30/1928	Rope Size: 1/2
Volts:	Complied: 04/30/1928	Entrances:
OWNER	OCCUPANT	
BURLINGTON DRAPERY CO	BURLINGTON DRAPERY CO	
227 UNION AVE.	227 UNION AVE.	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 12/29/2016	Type Inspection Removed	Certificate Status Not Issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	----------------------------------	-------------------------	--------------------

1

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: N/A

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

BURLINGTON DRAPERY CO
227 UNION AVE.
BURLINGTON, NC, 27215