



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17003-73-5781
State Number
1036

EQUIPMENT INSPECTED

State Number: 1036	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: WESTBROOK	Speed: 50
Landings: 2	Installed: 12/19/1947	Rope Size: 1/2
Volts: 220	Complied: 12/19/1947	Entrances: 2
OWNER	OCCUPANT	
STAN MARTIN 336-380-1797	WILLOWBROOK HOISERY CO	
PO BOX 2005	413 TUCKER ST	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 01/03/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

2.14.7.1.4	Put the car top light in working order.
8.11.2.3	Perform a 5 year full load safety test
2.14.7.1	Put the car lights in proper working order.
8.6	Provide current fire exstinguisher in machine room

Items must be corrected by: 03/02/2017

Elevator Name: STAN MARTIN 336-380-1797

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainance with current codes.

Violations pointed out to: Maintenance

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

STAN MARTIN 336-380-1797
PO BOX 2005
BURLINGTON, NC, 27215