

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17004-73-0998 State Number 24169

		EQUIPMENT INSPECTED			
State Number: 24169 Type of Unit: Passe		ssenger	Floor to Floor: 1 to 3		
Capacity: 2500 Manuf: THYSSEN		N KRUPP	Speed: 100		
Landings: 3	Installed: 09/20/2006		Rope Size: 0		
Volts: 208 Complied: 09/20/20		/2006	Entrances: 1		
OWNER		OCCUPANT			
SNR 27 CEDAR RIDGE OWNER LLC		CEDAR RIDGE RETII	REMENT CENTER		
5885 MEADOWS RD STE 500		2680 MEBANE STREE	2680 MEBANE STREET		
LAKE OSWEGO, OR, 97035		BURLINGTON, NC, 2	7215		
	IN	SPECTION INFORMATION			
Inspection Date 01/04/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE	
		VIOLATIONS			
Items must be corrected by: 03 Notify the Elevator Bureau in writi complainace with current codes. Violations pointed out to: Mainten	ng on Corrected Violations Form	when the following corrections hav	re been made in order to br		
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	SNR 27 CEDAR RIDGE O 5885 MEADOWS RD STE LAKE OSWEGO, OR, 970	500		