

THIS IS NOT AN

INVOICE

An invoice will be mailed to:

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17006-73-3267 State Number 24230

	I	EQUIPMENT INSPECTED			
State Number: <b>24230</b> Capacity: 2000 Landings: 3	Manuf: OTIS	Type of Unit: Passenger Manuf: OTIS Installed: 12/18/2006		Floor to Floor: 1 to 3 Speed: 125 Rope Size: 0	
Volts: 208 Complied: 12/18/20		8/2006	Entrances: 1		
OWNER		OCCUPANT			
ELON UNIVERSITY		OAKS BUILDING (D)			
803 HAGGARD AVENUE		1001 ELON COMMONS DR			
ELON, NC, 27244		ELON, NC, 27244			
	IN	SPECTION INFORMATION			
Inspection Date 01/06/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE	
·		VIOLATIONS			
5.1.21.1	Put the in car alarm bell in working ord	er.			
8.6 8.6	Machine room not to be used for storag Place in case of fire sign at each landing	e			
	Place in case of fire sign at each landing	e e g	Name: BUILDING (D)		
8.6  Items must be correct	Place in case of fire sign at each landing the state of the sign at each landing the state of the sign at each landing th	e g Elevator		ng your equipment into	

ELON UNIVERSITY

ELON, NC, 27244

803 HAGGARD AVENUE