



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17011-73-3969
State Number
24933

EQUIPMENT INSPECTED

State Number: 24933	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: THYSSEN KRUPP	Speed: 80
Landings: 2	Installed: 09/10/2007	Rope Size:
Volts: 480	Complied: 09/10/2007	Entrances: 1
OWNER	OCCUPANT	
R K HOSPITALITY GROUP	COLONNADES DINING (LOBBY)	
100 WOODLAKE PARKWAY	193 DALTON MCMICHAEL DR	
KINGS MOUNTAIN, NC, 28086	ELON, NC, 27244	

INSPECTION INFORMATION

Inspection Date 01/11/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

VIOLATIONS

2.2.5.1	Put the pit lights in proper working order.
8.6.4.13.1[1]	Properly maintain door restrictors, where required.
8.6.1.4.1[a]	Properly document maintenance records
8.6	Place fire service key switch in proper working order
8.6	Provide fire service light on main landing
8.6	Clean pit
8.6	Remove water from pit

Items must be corrected by: 03/11/2017

Elevator Name: COLLANADES lobby

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Rick

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

R K HOSPITALITY GROUP
100 WOODLAKE PARKWAY
KINGS MOUNTAIN, NC, 28086