

THIS IS NOT AN INVOICE

An invoice will be mailed to:

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17013-73-1926 State Number 26329

	F	EQUIPMENT INSPECTED		
State Number: 26329 Capacity: 2100 Landings: 2 Volts: 460 OWNER ELON UNIVERSITY 803 HAGGARD AVENUE ELON, NC, 27244	El 31	0/2009	Floor to Floor: 1 Speed: 80 Rope Size: 0 Entrances: 1	to 2
	INS	SPECTION INFORMATION		
Inspection Date 01/13/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
		VIOLATIONS		
8.6.4.13.1[1] 2.14.7.1.3 5.1.21.1 8.6 8.6	Properly maintain door restrictors, Put the in car emergency light in we Put the in car alarm bell in working Provide light cover in machine roor Provide catch buckets in elevator pi	orking order. order. n		
Items must be corrected	by: 03/13/2017	Elevator 1	Name: LINDER BLDG	
	n writing on Corrected Violations Form v			ing your equipment into

ELON UNIVERSITY 803 HAGGARD AVENUE

ELON, NC, 27244