

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17018-73-1089 State Number 28047

	I	EQUIPMENT INSPECTED			
State Number: 28047 Type of Unit		assenger	Floor to Floor: 1	Floor to Floor: 1 to 3 Speed: 125 Rope Size:	
Capacity: 4500	Manuf: SCHINDLER Installed: 08/01/2011		Speed: 125		
Landings: 3			Rope Size:		
Volts: 208	Complied: 08/01/2011		Entrances: 2		
OWNER		OCCUPANT			
EDG PROPERTIES LLC	ELON TOWN CENTER				
PO BOX 2676	130 N WILLIAMSON AVENUE				
GREENSBORO, NC, 27402		ELON, NC, 27244			
	IN	SPECTION INFORMATION			
Inspection Date 01/18/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE	
		VIOLATIONS			
Notify the Elevator Bureau in writing complainace with current codes. Violations pointed out to: Tammy A		when the following corrections hav	re been made in order to bri	ing your equipment into	
THIS IS NOT AN	o make changes to the invoice ma	ailing address please call: 919-733-	0372		
DILLOTOR	n invoice will be mailed to:	EDG PROPERTIES LLC			

GREENSBORO, NC, 27402