



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**17023-73-4269**  
State Number  
**15587**

EQUIPMENT INSPECTED

State Number: <b>15587</b>	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 4500	Manuf: THYSSEN KRUPP	Speed: 100
Landings: 2	Installed: 03/07/1995	Rope Size:
Volts: 480	Complied: 02/21/2002	Entrances: 1
OWNER	OCCUPANT	
KERNODLE CLINIC	KERNODLE CLINIC #3 RC	
1234 HUFFMAN MILL RD	1234 HUFFMAN MILL RD	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 01/23/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.6.4.13.1[[]]	Properly maintain door restrictors, where required.
8.6	Replace burned out light bulbs in elevstor cab

Items must be corrected by: 03/23/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Chris Kidd

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

KERNODLE CLINIC  
1234 HUFFMAN MILL RD  
BURLINGTON, NC, 27215