

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17044-66-0998 State Number 19883

2

EQUIPMENT INSPECTED State Number: 19883 Type of Unit: Passenger Floor to Floor: 1 to 2 Capacity: 2100 Manuf: THYSSEN KRUPP Speed: 95 Landings: 2 Installed: 08/13/2001 Rope Size: 0 Volts: 208 Complied: 08/23/2001 Entrances: 1 OWNER OCCUPANT ALEXANDER COUNTY SCHOOLS ALEXANDER CENTRAL HIGH SCHOOL 700 LILEDOUN ROAD 241 SCHOOL AVENUE TAYLORSVILLE, NC, 28681 TAYLORSVILLE, NC, 28681 INSPECTION INFORMATION Inspection Date Type Inspection Certificate Status County Inspector ALEXANDER 02/13/2017 Routine Re-issued 66 - Pacitti VIOLATIONS 2.12.5 Put the car door restricting device in proper working order. 8.11.3.2.1 Perform the annual relief valve test AND PLACE TAG ON ALL UNITS 8.6.4.7.1 Clean the elevator pit. 8.6.4.9 Clean the elevator car top. 8.6.4.15 Take steps to place the car emergency light in proper working order. (telephone, ventilation) 2.14.1.5.1 Secure the car top emergency exit. 8.6.4.13.1[i] Properly maintain clutches, engaging vanes, retiring cams, and engaging rollers. BROKEN DOOR CLUTCH BOTTOM SPRING NOTE THE CAR DOOR NEEDS ADJ OPENING SLOW THIS IS A 2 SPEED DOOR OPERATION LETS GET IT FIXED Items must be corrected by: 04/01/2017 Elevator Name: #2

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

complainace with current codes.

Violations pointed out to: ALEXANDER CO SCHOOLS828-632-7063

ALEXANDER COUNTY SCHOOLS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into

An invoice will be mailed to: 700 LILEDOUN ROAD TAYLORSVILLE, NC, 28681

Inspector