

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17046-48-1191 State Number 30726

EQUIPMENT INSPECTED					
State Number: 30726	Manuf: OTIS			Floor to Floor: 1 to 2 Speed: 100 Rope Size: Entrances: 1	
Capacity: 2500			•		
Landings: 2	Installed: 02/15				
Volts: 208	Complied: 02/15/2017		Entrances: 1		
OWNER	OCCUPANT				
LOCKWOOD FOLLY POA	LOCKWOOI	NTER CAR 1			
111 CLUBHOUSE DRIVE 19 CLUBHOUSE DRIVE					
SUPPLY, NC, 28462	SUPPLY, NC, 28462				
	INS	SPECTION INFORMATION			
Inspection Date 02/15/2017	Type Inspection New	Certificate Status Issued	Inspector 48 - Martin	County BRUNSWICK	10
		VIOLATIONS			
Elevator Name: # 1					
Notify the Elevator Bureau in wicomplainace with current codes.	riting on Corrected Violations Form v	when the following corrections	have been made in order to	bring your equipment into	
Violations pointed out to: JOE [OTIS]					
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	LOCKWOOD FOLLY I 111 CLUBHOUSE DRI SUPPLY, NC, 28462			