



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17047-73-1627
State Number
24721

EQUIPMENT INSPECTED

State Number: 24721	Type of Unit: Passenger	Floor to Floor: 1 to 4
Capacity: 5000	Manuf: TKE	Speed: 350
Landings: 4	Installed: 06/25/2008	Rope Size: 3/4
Volts: 480	Complied:	Entrances: 1
OWNER	OCCUPANT	
LABCORP	LABCORP HEADQUARTERS	
271 E FRONT ST	531 S SPRING STREET	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 02/16/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.6.4.7.1	Clean the elevator pit.
2.14.4.2.1	Put the car door gate switch in proper working order.
2.14.7.1.3	Put the in car emergency light in working order.
5.1.21.1	Put the in car alarm bell in working order.

Items must be corrected by: 03/18/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: F Linch

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

LABCORP
271 E FRONT ST
BURLINGTON, NC, 27215