



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17051-73-2881
State Number
12214

EQUIPMENT INSPECTED

State Number: 12214	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: THYSSEN KRUPP	Speed: 100
Landings: 2	Installed: 08/20/1987	Rope Size:
Volts: 200	Complied: 08/20/1987	Entrances: 1
OWNER	OCCUPANT	
CHANDLER CONCRETE	CHANDLER CONCRETE	
PO BOX 131	1006 CHURCH ST	
BURLINGTON, NC, 27216-0131	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 02/20/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.6.4.13.1[] Properly maintain door restrictors, where required.

Items must be corrected by: 03/22/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: ken.meadows@chandlerconcrete.com

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

CHANDLER CONCRETE
PO BOX 131
BURLINGTON, NC, 27216-0131