



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17051-73-3253
State Number
29716

EQUIPMENT INSPECTED

State Number: 29716	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 1400	Manuf: CUSTOM ELEV INC	Speed: 30
Landings: 2	Installed: 03/09/2015	Rope Size:
Volts: 220	Complied: 03/09/2015	Entrances: 1
OWNER	OCCUPANT	
BURLINGTON CHRISTIAN CHURCH	BURLINGTON CHRISTIAN CHURCH	
301 TRAIL FOUR	301 TRAIL FOUR	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 02/20/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.11.3.2.1	Provide the annual relief valve and system pressure test.
2.11.3.1	Adjust the elevator hoistway doors to self close fully.
2.27.1.1.2	Put the in car emergency telephone in proper working order.
8.6	Provide grate over sump pump in pit
8.6	Tighten car handrail

Items must be corrected by: 03/22/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: bcjnap@yahoo.com

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

BURLINGTON CHRISTIAN CHURCH
301 TRAIL FOUR
BURLINGTON, NC, 27215