

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927

Report Number 17051-73-5633 State Number 10613

1

EQUIPMENT INSPECTED

State Number: 10613 Capacity: 2500 Landings: 8 Volts: 200

OWNER BEACON MANAGEMENT

PO BOX 29229

GREENSBORO, NC, 27429-9229

Type of Unit: Passenger Floor to Floor: B to 7

Manuf: SOUTHERN Speed: 200 Installed: 09/22/1983 Rope Size: 5/8 Complied: 11/10/2005 Entrances: 1

OCCUPANT

ALAMANCE PLAZA 111 MAPLE AVE

BURLINGTON, NC, 27215

INSPECTION INFORMATION

Certificate Status Inspector Inspection Date Type Inspection County ALAMANCE 02/20/2017 Routine Re-issued 73 - James

VIOLATIONS

2.27.1.1.2 Put the in car emergency telephone in proper working order. 8.6.4.13.1[1] Properly maintain door restrictors, where required. 2.27.1.1.2 Put the in car emergency telephone in proper working order.

Items must be corrected by: 03/22/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: alamance@beacon-nc.com Inspector __

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

An invoice will be mailed to:

BEACON MANAGEMENT PO BOX 29229

GREENSBORO, NC, 27429-9229