



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17052-73-1763
State Number
19572

EQUIPMENT INSPECTED

State Number: 19572	Type of Unit: Passenger	Floor to Floor: B to 2
Capacity: 2000	Manuf: CANTON	Speed: 98
Landings: 3	Installed: 12/06/2000	Rope Size:
Volts: 220	Complied: 12/06/2000	Entrances: 1
OWNER	OCCUPANT	
LAB CORP	LAB CORP "MAPLE AVE BDLG"	
348 S MAIN ST	231 MAPLE AVE	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 02/21/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

2.14.7.1.3	Put the in car emergency light in working order.
5.1.21.1	Put the in car alarm bell in working order.

Items must be corrected by: 03/23/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Lab Corp

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

LAB CORP
348 S MAIN ST
BURLINGTON, NC, 27215