



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17052-73-2313
State Number
15329

EQUIPMENT INSPECTED

State Number: 15329	Type of Unit: Passenger	Floor to Floor: 1 to 3
Capacity: 4000	Manuf: THYSSEN KRUPP	Speed: 125
Landings: 3	Installed: 01/21/1994	Rope Size:
Volts: 200	Complied: 03/01/1994	Entrances: 2
OWNER	OCCUPANT	
LAB CORP	LAB CORP "CENTRAL FURNITURE"	
348 S MAIN ST	448 S MAIN ST	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27216	

INSPECTION INFORMATION

Inspection Date 02/21/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.6	Put cab lights in proper working order
8.6	Place alarm bell in working order
8.6	Place emergency light in working order
8.6	Replace worn pickup rollers at top landing
8.6	Tighten loose pickup rollers on bottom landing

Items must be corrected by: 03/23/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Lab Corp

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

LAB CORP
348 S MAIN ST
BURLINGTON, NC, 27215