



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17053-73-3289
State Number
17441

EQUIPMENT INSPECTED

State Number: 17441	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: THYSSEN KRUPP	Speed: 95
Landings: 2	Installed: 04/02/1998	Rope Size:
Volts: 200	Complied: 04/02/1998	Entrances: 1
OWNER	OCCUPANT	
ALAMANCE CO SCHOOLS	ALAMANCE SCHOOL OFFICES	
1712 VAUGHAN RD	1712 VAUGHN RD	
BURLINGTON, NC, 27217	BURLINGTON, NC, 27217	

INSPECTION INFORMATION

Inspection Date 02/22/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.6.1.4.1[a]	Properly document maintenance records
8.6	Remove oil/water from sump pit
8.6	Replace worn pickup rollers on bottom hoistway door
8.6	Provide in case of fire sign at each landing

Items must be corrected by: 03/24/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: kina_bostick@abss.k12.nc.us

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ALAMANCE CO SCHOOLS
1712 VAUGHAN RD
BURLINGTON, NC, 27217