

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17053-73-5168 State Number H1854

	E	EQUIPMENT INSPECTED			
State Number: H1854	Type of Unit:	Hand Lift	Floor to Floor: 1	to 2	
Capacity: 750	Manuf: ACCESS		Speed: 10		
Landings: 1	Installed: 05/1	Installed: 05/17/2007		Rope Size: 0	
Volts: 220	Complied: 05/	Complied: 05/17/2007			
OWNER		OCCUPANT			
REFUGE TEMPLE CHURCH		REFUGE TEMPLE CHURCH			
152 N MAIN STREET		152 N MAIN STREET			
BURLINGTON, NC, 27217		BURLINGTON, NC	, 27217		
	INS	SPECTION INFORMATION			
Inspection Date 02/22/2017	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 73 - James	County ALAMANCE	
		VIOLATIONS			
Items must be corrected by: 03/2					
Notify the Elevator Bureau in writing complainace with current codes.	g on Corrected Violations Form v	when the following corrections hav	re been made in order to br	ing your equipment into	
Violations pointed out to: emsquaredemg@yahoo.com			Inspector		
	o make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE AI	n invoice will be mailed to:	REFUGE TEMPLE CHURO 152 N MAIN STREET BURLINGTON, NC. 27217			