

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17060-54-2160 State Number 8543

8

EQUIPMENT INSPECTED					
State Number: <b>8543</b> Capacity: 12000 Landings: 2 Volts: 480 OWNER PERDUE INC. PO BOX 1537 SALISBURY, MD, 21802		Type of Unit: Freig Manuf: SOUTHEF Installed: 02/03/19 Complied: 02/14/2	N 76		
		INSPI	ECTION INFORMATION		
		Type Inspection Routine	Certificate Status Not Issued	Inspector 54 - Green	County BERTIE
			VIOLATIONS		
8.6.1.4.1[a] 8.11.1.6 8.11.3.2.1 8.6.4.7.1 8.6.4.7.4 8.6.5.5.1 8.6.4.13.1 2.11.11.5 2.12.2.4.1 NOTE	Provide the appropriate test tag.  Provide the annual relief valve and system pressure test.  Clean the elevator pit.  Remove the oil from the pit floor.  Where valves and cylinders use packing glands or seals, they shall be examined and maintained to prevent excessive loss of fluid.  All landing and car-door or gate mechanical and electrical components shall be maintained to ensure safe and proper operation.  Replace or repair the damaged hoistway doors. 1st floor handle has rough edges.  Install the missing interlock covers where needed.  INSTALL CAR TOP JBOX 4X4 COVER				
Notify the El complainace	ust be corrected by levator Bureau in v with current code: pinted out to: Mr.l	vriting on Corrected Violations Form whos. Lewis manager	-	Inspector	
THIS IS NOT AN INVOICE		An invoice will be mailed to:	PERDUE INC. PO BOX 1537 SALISBURY MD 21802		