

INVOICE

An invoice will be mailed to:

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17067-73-3787 State Number 6590

	E	EQUIPMENT INSPECTED			
State Number: 6590		Type of Unit: Passenger		Floor to Floor: 1 to 2	
Capacity: 3500	Manuf: SOUTHERN		Speed: 75		
Landings: 3	Installed: 06/23/1970		Rope Size:		
Volts: 480	s: 480 Complied: 07/01/2003		Entrances: 2		
OWNER		OCCUPANT			
ALAMANCE CO SCHOOLS CUMMINGS SENIOR HIGH SCHOOL					
1712 VAUGHAN RD		2200 MEBANE ST			
BURLINGTON, NC, 272	17	BURLINGTON, NC, 27217			
	INS	SPECTION INFORMATION			
Inspection Date 03/08/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE	
		VIOLATIONS			
8.6.1.4.1[a]	Properly document maintenance record	ds			
8.6	Replace missing top slide guide				
8.6	Provide "in case of fire" sign at each landing				
8.6	Clean elevator pit				
8.6	Replace worn pickup rollers on bottom hoistway door				
8.6	Replace damaged cable on bottom of car				
8.6	Replace missing slide guide on bottom	of car			
8.6	Perform annual relief valve test				
8.6	Provide clear path to elevator equipment	nt room			
Items must be corrected	i by: 04/07/2017				
Notify the Elevator Bureau complainace with current co	in writing on Corrected Violations Form vodes.	when the following corrections have	e been made in order to br	ing your equipment in	
Violations pointed out to: School maintenance			Inspector		
	To make changes to the invoice ma	• •	0372		
THIS IS NOT AN	THIS IS NOT AN ALAMANCE CO SCHOOLS				

1712 VAUGHAN RD BURLINGTON, NC, 27217