

INVOICE

An invoice will be mailed to:

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17072-66-0980 State Number 14194

2

		EQ	UIPMENT INSPECTED			
Stata Nava-1	ham 14104	Type of Unit: Passer		Eleante El-	1 to 2	
•		Manuf: THYSSEN	· ·		Floor to Floor: 1 to 2	
1 3			Manuf: THYSSEN KRUPP Installed: 07/25/1991		Speed: 100 Rope Size: 0	
			Complied: 07/25/1991		Entrances: 1	
		Complied. 07/23/19	-		Littanees. 1	
OWNER			OCCUPANT			
ALEXANDER COUNTY SCHOOLS		OLS	BETHLEHEM ELEMENTARY SCHOOL			
700 LILEDOUN ROAD			7900 N.C. HWY 127			
TAYLOR	SVILLE, NC, 28681		TAYLORSVILLE, NC,	28681		
		INSP	ECTION INFORMATION			
Inspection Date 03/13/2017		Type Inspection Routine	Certificate Status Re-issued	Inspector 66 - Pacitti	County ALEXANDER	
			VIOLATIONS			
8.6.4.15	Take steps to place the car emergency light in proper working order. (telephone, ventilation)					
5.1.21.1	Put the in car alarm bell in working order.					
2.14.7.1.4	Put the car top light in working order.SWITCH IS BROKEN					
8.6.4.8.1	Clean the elevator machine room.					
8.6.4.9	Clean the elevator car top.					
8.11.3.2.1	Provide the annual relief valve and system pressure test.					
8.11.1.6	11 1 8					
8.11.3.2.1	Perform the annual relief valve test					
NOTE FIX ADJ CAR DOOR FROM SLAMING IN OPEN ITS TOO FAST. THIS VIOLATIONS NEED					ESSED	
Items m	nust be corrected by: 03/	23/2017				
	Elevator Bureau in writir with current codes.	ng on Corrected Violations Form wh	nen the following corrections h	ave been made in order to l	oring your equipment in	
Violations p	pointed out to: drobertso	on@alexander.k12.nc.us				
		o make changes to the invoice mail				
THI	S IS NOT AN		ALEXANDER COUNTY SCHOOLS			

700 LILEDOUN ROAD

TAYLORSVILLE, NC, 28681