



INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17072-66-1448
State Number
11208

EQUIPMENT INSPECTED

State Number: 11208	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 4000	Manuf: ESCO	Speed: 50
Landings: 2	Installed: 01/09/1985	Rope Size: 0
Volts: 480	Complied: 01/09/1985	Entrances: 1
OWNER	OCCUPANT	
JIM MOORE	HANCOCK & MOORE FURNITURE	
P.O. BOX 3444	127 NORTH RINK DAM ROAD	
HICKORY, NC, 28603	TAYLORSVILLE, NC, 28603	

INSPECTION INFORMATION

Inspection Date 03/13/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 66 - Pacitti	County ALEXANDER
-------------------------------	----------------------------	---------------------------------	---------------------------	---------------------

2

VIOLATIONS

8.11.3.2.1	Perform the annual relief valve test
8.6.4.8.4	Take steps to keep the machine room access door closed and locked at all times.repair so door closes
8.6.4.7.1	Clean the elevator pit.
5.1.21.1	Put the in car alarm bell in working order.

Items must be corrected by: 04/12/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: HANCOCK&MOORE 828-495-8235

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

JIM MOORE
P.O. BOX 3444
HICKORY, NC, 28603