



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17072-73-2884
State Number
21988

EQUIPMENT INSPECTED

State Number: 21988	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: THYSSEN KRUPP	Speed: 80
Landings: 2	Installed: 10/16/2003	Rope Size: 0
Volts: 208	Complied: 10/16/2003	Entrances: 1
OWNER	OCCUPANT	
MEBANE POLICE STATION	MEBANE POLICE STATION	
116 W CENTER STREET	116 W CENTER STREET	
MEBANE, NC, 27302	MEBANE, NC, 27302	

INSPECTION INFORMATION

Inspection Date 03/13/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.11.3.2.1	Provide the annual relief valve and system pressure test.
8.6	Place car door restrictor in working order
8.6	Machine room not to be used for storage
8.6	Place cartop light in working order

Items must be corrected by: 04/12/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: lcurrie@mebanepd.com

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

MEBANE POLICE STATION
116 W CENTER STREET
MEBANE, NC, 27302