

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17073-48-4244 State Number 22316

		EQUIPMENT INSPECTED			
State Number: 22316 Type of Unit: P		ssenger	Floor to Flo	Floor to Floor: 1 to 3	
Capacity: 2100	Manuf: THYSSEN KRUPP Installed: 10/20/2004		Speed: 65 Rope Size: Entrances: 1		
Landings: 3					
Volts: 240 Complied: 11/04/2004		/2004			
OWNER		OCCU	OCCUPANT		
THE WOODLANDS @ CRO	OW CREEK	CROV	V CREEK CONDOS #3		
10255 BEACH DR SW		290 W	OODLANDS WAY, SW		
CALABASH, NC, 28467		CALABASH, NC, 28467			
	IN	ISPECTION INFORMATION			
Inspection Date 03/14/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	
		VIOLATIONS			
	s from machine room (machinery spa				
Items must be corrected by	: 04/14/2017				
Notify the Elevator Bureau in volume omplainace with current codes	writing on Corrected Violations Form s.	when the following corrections	s have been made in order to	bring your equipment into	
Violations pointed out to: UNAVAILABLE					
	To make changes to the invoice m				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	THE WOODLANDS @ 10255 BEACH DR SW CALABASH, NC, 2846			