NCDOL NCDOL N. Department of labor

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17075-48-0476 State Number 23971

G			EQUIPMENT INSPECTED			
State Number: 239		Type of Unit: F	assenger	Floor to Floor: 1 to 3		
Capacity: 2000	pacity: 2000 Manuf: THYSSEN KRUPP			Speed: 55		
Landings: 3 Installed: 05/17/2006			7/2006	06 Rope Size: 0		
Volts: 230 Complied: 05/17			7/2006 Entrances: 1			
OWNER			OCCUPANT			
THE WOODLANDS @ CROW CREEK			CROW CREEK CONDO #9			
10255 BEACH DR SW			235 WOODLANDS WAY			
CALABASH, NC, 28467			CALABASH, NC, 28467			
			NSPECTION INFORMATION			
Inspection Date 03/16/2017		Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	
			VIOLATIONS			
8.6.4.7.1	Clean the elevator pit. [COBWEBS]					
2.2.5.1	Put the pit lights in proper working order. [2ND YR]					
2.27.1.1.2	7.1.1.2 Put the in car emergency telephone in proper working order. [2ND YR]					

Items must be corrected by: 04/16/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: UNAVAILABLE Inspector _____

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

THE WOODLANDS @ CROW CREEK
An invoice will be mailed to: 10255 BEACH DR SW

10255 BEACH DR SW CALABASH, NC, 28467