

Violations pointed out to: Ken Mcadams 336 226 1181

An invoice will be mailed to:

THIS IS NOT AN

INVOICE

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17075-73-1058
State Number 16068

	I	EQUIPMENT INSPECTED		
tate Number: 16068 Type of Unit: Pa		ssenger Floor to Floor: 1 to 2		1 to 2
Capacity: 4500 Manuf: THYSSEN KRUPP		N KRUPP	Speed: 125	
Landings: 2 Installed: 09/14/1995		995	Rope Size:	
Volts: 480	s: 480 Complied: 09/14/1995		Entrances: 1	
OWNER		OCCUPANT		
KIRKPATRICK MEDICAL GROUP LLC		KIRKPATRICK MEDICAL GROUP		
1041 KIRKPATRICK RD		1041 KIRKPATRICK RD		
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215		
	IN	SPECTION INFORMATION		
Inspection Date 03/16/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
		VIOLATIONS		
8.6 Repair leak in oil line				

KIRKPATRICK MEDICAL GROUP LLC

1041 KIRKPATRICK RD

BURLINGTON, NC, 27215

To make changes to the invoice mailing address please call: 919-733-0372

Inspector ___