



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17079-73-2344
State Number
5446

EQUIPMENT INSPECTED

State Number: 5446	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 2000	Manuf: SOUTHERN	Speed: 50
Landings: 2	Installed: 10/24/1967	Rope Size:
Volts: 220	Complied: 11/10/1965	Entrances: 1
OWNER	OCCUPANT	
WRIGHTENBERRY MILLS INC	WRIGHTENBERRY MILLS INC	
910 CLEVELAND	910 CLEVELAND	
BURLINGTON, NC, 27217	BURLINGTON, NC, 27217	

INSPECTION INFORMATION

Inspection Date 03/20/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.6.4.7	Remove the water from the pit floor and take steps to prevent its re-entry.
8.6	Provide self closing machine room door

Items must be corrected by: 04/19/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: customer.service@wrightsock.com

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372
An invoice will be mailed to:
WRIGHTENBERRY MILLS INC
910 CLEVELAND
BURLINGTON, NC, 27217