NCDOL NCDOL M. Department of labor

THIS IS NOT AN

INVOICE

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17094-48-5954 State Number 24566

			EQUIPMENT INSPECTED			
State Number: 24566 Type of Unit: F		Passenger	Floor to Flo	por: 1 to 3		
Capacity: 2000 Manuf: THYS			1			
Landings: 3 Installed: 02/21/			/2007 Rope Size: 0		0	
Volts: 230 Complied:				Entrances: 1		
OWNER			OCC	UPANT		
THE WOODLANDS @ CROW CREEK			CRO	CROW CREEK - BLDG #13		
10255 BEACH DR SW			395 S CROW CREEK DRIVE			
CALABASH, NC, 28467			CALABASH, NC, 28467			
			INSPECTION INFORMATION			
Inspection Date 04/04/2017		Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK 1	
			VIOLATIONS			
2.7.3.4.1 2.7.9.1		osing self-locking machine room ne room or space lights in working	/ space door. g order. 200 lx or 19 fc @ the mac	hine room floor.		
Notify the Elecomplainace	ust be corrected by: (evator Bureau in writh current codes.) with out to: UNAV	iting on Corrected Violations For	m when the following corrections	have been made in order to	bring your equipment into	

10255 BEACH DR SW

CALABASH, NC, 28467

THE WOODLANDS @ CROW CREEK

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to: