

Violations pointed out to: mazurm@labcorp.com

THIS IS NOT AN

INVOICE

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17094-73-1540 State Number 13709

EQUIPMENT INSPECTED					
State Number: 13709 Capacity: 4000 Landings: 3 Volts: 460	Manuf: THYSSEN Installed: 09/19/19	Manuf: THYSSEN KRUPP S Installed: 09/19/1991 H		Floor to Floor: 1 to 3 Speed: 80 Rope Size: Entrances: 2	
OWNER LAB CORP ATTN STEVE THACKE BURLINGTON, NC, 272	R				
	INSI	PECTION INFORMATION			
Inspection Date 04/04/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE	
		VIOLATIONS			
	Clean the pit and the pit equipment. Adjust slide guides on car				
Items must be corrected	l by: 05/04/2017				
Notify the Elevator Bureau complainace with current co	in writing on Corrected Violations Form wholes.	hen the following corrections have	e been made in order to bri	ng your equipment into	

LAB CORP

ATTN STEVE THACKER BURLINGTON, NC, 27215

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

Inspector ___