



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17094-73-3980
State Number
27993

EQUIPMENT INSPECTED

State Number: 27993	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 3500	Manuf: OTIS	Speed: 100
Landings: 2	Installed: 08/29/2011	Rope Size:
Volts: 208	Complied:	Entrances: 1
OWNER	OCCUPANT	
LAB CORP	LAB CORP	
1447 YORK COURT	1447 YORK COURT	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 04/04/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.6	Place car lights in proper working order
8.6	Clean elevator pit
8.6	Perform annual pressure test

Items must be corrected by: 05/04/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: mazurm@labcorp.com

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:
LAB CORP
1447 YORK COURT
BURLINGTON, NC, 27215