

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17095-73-5214 State Number 15191

EQUIPMENT INSPECTED					
State Number: 15191 Capacity: 2500 Landings: 3	Type of Unit: Pa: Manuf: USEC Installed: 02/09/1	1994	Floor to Floor: 1 Speed: 115 Rope Size:	to 3	
Volts: 240	Complied: 02/09	/1994	Entrances: 1		
911 NORTH AVE	EN HOPE BAPTIST CHURCH I NORTH AVE		OCCUPANT GLEN HOPE BAPTIST CHURCH 911 NORTH AVE		
BURLINGTON, NC, 27217		BURLINGTON, NC			
	INSI	PECTION INFORMATION			
Inspection Date 04/05/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE	
		VIOLATIONS			
Items must be corrected by: 0					
Notify the Elevator Bureau in write complainace with current codes.	ing on Corrected Violations Form when	hen the following corrections have	ve been made in order to br	ng your equipment into	
Violations pointed out to: sherih@bellsouth.net			Inspector		
THIS IS NOT AN	To make changes to the invoice mail  An invoice will be mailed to:		0372 HURCH		