NCDOL NCDOL NA Department of later

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17115-48-0794 State Number 20633

	E	EQUIPMENT INSPECTED			
State Number: 20633	Type of Unit: Pass	Type of Unit: Passenger		oor: 1 to 4	
Capacity: 3000 Manuf: THYSSEN KRUPP		N KRUPP	PP Speed: 125		
Landings: 4	Installed: 02/06/2002		Rope Size:	Rope Size:	
Volts: 208 Complied: 02/08/2		Entrances: 1		1	
OWNER		OCCUPANT			
CAM		ISLANDER RESORT			
P.O. BOX 8126	3 BECKY ST.				
OCEAN ISLE BEACH, NC, 2840	69	OCEAN ISLE BEACH, NC, 28469			
	INS	SPECTION INFORMATION			
Inspection Date 04/25/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	
		VIOLATIONS			
Notify the Elevator Bureau in writing complainace with current codes.	ng on Corrected Violations Form v	when the following corrections	have been made in order to	bring your equipment into	
Violations pointed out to: UNAVA			Inspector		
Т	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN	CAM				
INVOICE A	An invoice will be mailed to:	P.O. BOX 8126 OCEAN ISLE BEACH, NC, 28469			