

THIS IS NOT AN INVOICE

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number **17116-48-2416** State Number **21905**

EQUIPMENT INSPECTED					
State Number: 2190	5 Type of U	Type of Unit: Passenger		or: G to 3	
1 7		THYSSEN KRUPP	Speed: 125		
		11/12/2003	Rope Size:	0	
Volts: 208	Complied	Complied: 11/12/2003 Entrances: 1 OCCUPANT ISLANDER RESORT - BLDG. #29			
OWNER					
CAM					
P.O. BOX 8126		4 JAN STREET OCEAN ISLE BEACH, NC, 28469			
OCEAN ISLE BEA	.CH, NC, 28469				
		INSPECTION INFORMATION			
Inspection D 04/26/2017	ate Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK 1	
		VIOLATIONS			
N/A SE	CURE HALL BUTTON PLATE [3RI				
Notify the Elevator B complainace with cur	rent codes.	ns Form when the following corrections		bring your equipment into	
Violations pointed ou	t to: UNAVAILABLE		Inspector		

P.O. BOX 8126 OCEAN ISLE BEACH, NC, 28469

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to: