

THIS IS NOT AN

INVOICE

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17123-48-2051 State Number 22009

EQUIPMENT INSPECTED					
State Number: 22009 Type of Unit: Pass		ssenger Floor to Floor: 1 to 2		oor: 1 to 2	
Capacity: 2000 Manuf: THYSSEN KRUPP			Speed: 65		
Landings: 2 Installed: 01/09/2004 Volts: 230 Complied: 01/09/2004		9/2004	1		
		09/2004			
OWNER		OCCUPA	OCCUPANT		
NANCY & ROLAND GILL	IAM	MCNEII	. CO.		
6102 E. OAK ISLAND DR.		6102 E C	6102 E OAK ISLAND DR		
OAK ISLAND, NC, 28465		OAK ISLAND, NC, 28465			
		INSPECTION INFORMATION			
Inspection Date 05/03/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK 1	
		VIOLATIONS			
2.27.1.1.1 8.6.4.19.2 (b)	Place the in-car Emergency Photo Provide the annual no load test.				
Items must be corrected by: 06/02/2017			Elevator Name: # 1		
complainace with current code		m when the following corrections		bring your equipment into	
Violations pointed out to: MG		Inspector			

NANCY & ROLAND GILLIAM

6102 E. OAK ISLAND DR. OAK ISLAND, NC, 28465

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to: